# Placing Jogs in a Dimension Line

This Tech Tip looks at how to add a jog into a dimension line to make they view more visible.

There are times when you wish to dimension a model and the spacing between dimensions is really tight and this makes it difficult to see where the dimension line actually attaches to.

The first step in the process is to select the dimension which you wish to apply the jog to:

Next, hold down the Alt key and click on the highlighted dimension line where you wish the jog to start:

Finally, select the handle point on the jog to place the dimension line where it is more visible (placing extra jogs, as required):